


EXAMPLE PROCESS FLOW CHART



NEBRASKA SCREW PRESS



SKINS IN WATER
WASH (OPTIONAL)



PRESSING → WATER TO ION EXCHANGE



WET SKINS TO DRYER



50% MOISTURE REMOVAL

WASHED, DRY SKINS TO FLOUR GRINDING

COLOR (ANTHOCYANINS)



SUGARS → COGNAC

PRODUCTION